






8x
5-500




2x
546500146



8x
5,0-60SU




8x
19500000




2x
189547343


1




2






3




A




B




4




5






6




A




B




7









8




9




10





11





12





13





13A




13B




13C



14



15



Dansani A/S
 Finlandsvej 8
 DK-6100 Haderslev
 Tel.: +45 73 22 29 00
 Mail: mail@dansani.dk

www.dansani.com www.scanbad.com



5 713804 440952

No. 1434 250130 Rev. 01